d&b ArraySight V3.00.33 Firmware, Release notes

A firmware update of the ArraySight sender unit is performed using the d&b R1 V2 or V3 Remote control software.

To do this, start R1, navigate to the Service view, select the Firmware tab and download the latest version.

Updating the firmware of the ArraySight sender unit requires an Ethernet connection to R1. In this case make sure the network does not get interrupted during the process. An interruption during the update process does not harm the device, just restart R1 and repeat the update.

Changes of V3.00.33 against previous V3.00.20

– Device discovery in R1 further improved.

05/2026

Changes of V3.00.20 against previous V2.00.03

– Improved device discovery in R1.
– Reduced power consumption for longer battery life.
– New Host name format matching the rest of the d&b products.
– Improved robustness of serial communication.

11/2021

Changes of V2.00.03 against previous V1.02.00

– TCP/IP connection handling improved to fix a large number of R1 timeout issues related to ArraySight.

09/2018

Changes of V1.02.00 against previous V1.00.02

– Remote-ID can be assigned in R1 Service view.
– Two OCA connections are possible at a time.

02/2018

V1.00.02

First release of ArraySight firmware.

08/2017

DOC05372 (05/2026) © d&b audiotechnik GmbH & Co. KG