


Windows 8 and d&b R60/D6 driver installation

With Windows 8 or higher, the "Driver signature enforcement" option is enabled by default. For this reason, the d&b R60/D6 drivers will not be accepted.

Although the installation dialog indicates that the driver is installed, the "Device manager" cannot identify the device.



d&b is working on obtaining certification of the R60/D6 drivers from Microsoft and therefore d&b recommends to regularly check the d&b website for driver updates.

To disable the "Driver signature enforcement" in **Windows 8**, perform the following workaround procedure.

1. Open the "Charms" bar in Windows 8 and select "Settings".
2. Select "Change PC Settings".
3. Select "General", scroll to the bottom of the General page and select "Restart Now" under "Advanced Start-Up".
4. After reboot, from the "Choose an option" screen, select "Troubleshoot".
5. From the "Troubleshoot" screen, select "Advanced options".
6. From the "Advanced options" screen, select "Startup Settings".
7. Click the "Restart" button.
⇒ The system will restart and switch to the "Advanced Boot Options" screen.
8. From the "Startup Settings" screen, select "Disable driver signature enforcement" by pressing the corresponding number key or function key as shown in the graphic opposite.
⇒ The d&b R60/D6 drivers can now be installed in the same way as in Windows 7.

